



Field Service Bulletin – FSB # 161103

Flexible Cord Heaters

Product(s) Applied To: 120V/1500W 120V/1800W, and 240V/3500W heaters with flexible power cords.

Submitted By: Steven Burns

Date: November 23, 2016

Reason:

Due to a compliance issue, we are no longer producing 120V/1,500W, 120V/1,800W, or 240V/3500W heaters with the flexible cord option. Instead, these models will be produced with wire in conduit. Please see the list of affected model numbers below. We will continue to offer flexible cords on 120V/1000W and 240V/2500W heaters. You do not need to replace heaters currently in service. We apologize for any inconvenience this may cause you.

Alternatives: Equivalent heaters with wire in conduit are the recommended replacement. When affected models are ordered, they will now come with wire in conduit instead of flexible cords. For questions or recommendations, please contact our inside sales team.

Pictures:



Flexible cable



Conduit

Affected Products:

LSA*1.51*
LSA*1.81*
LSA*3.52*
LTA*1.51*
LTA*1.81*
LTA*3.52*
SA*1.51*
SA*1.81*
SA*3.52*
TA*1.51*
TA*1.81*
TA*3.52*
STA*1.51*
STA*1.81*
STA*3.52*
TTA*1.51*
TTA*1.81*
TTA*3.52*

Field Service Bulletin – FSB cont.

Approval of Field Service Bulletin		FSB 161103	
Signature		Date	Approval
Field Service Manager:			<input type="checkbox"/> Yes / <input type="checkbox"/> No
Engineering:			<input type="checkbox"/> Yes / <input type="checkbox"/> No
Quality:			<input type="checkbox"/> Yes / <input type="checkbox"/> No
Production:			<input type="checkbox"/> Yes / <input type="checkbox"/> No
Comments:			