



Field Service Bulletin – FSB # 170301

HX 600V 5/6KW Heaters

Product(s) Applied To: 600V HX heaters with 5 or 6kw elements

Submitted By: Steven Burns

Date: March 29, 2017

Reason:

Due to a supplier issue, we are no longer able to produce 600V versions of HX heaters with 5 or 6kw elements. Smaller wattages are still available, as are lower voltages. We apologize for any inconvenience this may cause you.

Alternatives:

We will continue to manufacture 600V HX heaters with 4.5kw and smaller elements, so other heater configurations with more elements (2HX*, 3HX*, or 6HX*) or a greater quantity of smaller heaters may be acceptable substitutes. For recommendations on replacements, please contact our inside sales team for suggestions for your application.

Product Photo:



Affected Products:

HX56*
HX66*
HXO56*
HXO66*
HXOL56*
HXOL66*
HXF56*
HXF66*
2HX106*
2HX126*
2HXO106*
2HXO126*
2HXOL106*
2HXOL126*
3HX156*
3HX186*
3HXO156*
3HXO186*
3HXOL156*
3HXOL186*

Field Service Bulletin – FSB cont.

Approval of Field Service Bulletin	FSB 170301	
Signature	Date	Approval
Field Service Manager:		<input type="checkbox"/> Yes / <input type="checkbox"/> No
Engineering:		<input type="checkbox"/> Yes / <input type="checkbox"/> No
Quality:		<input type="checkbox"/> Yes / <input type="checkbox"/> No
Production:		<input type="checkbox"/> Yes / <input type="checkbox"/> No
Comments:		